UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,851,871 B2

Page 1 of 1

DATED

: February 8, 2005

INVENTOR(S) : Shinichi Masuda

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6,

Line 39, insert the following paragraph:

-- Here, a spring 153 engages an angular hole 148b in the second lens holder 148, and urges cam pin 148a outward in radial direction with respect to the second lens holder 148. This eliminates play between the third cam grooves 144c and cam pin 148a. --.

Column 8,

Line 29, delete "39" and insert -- 49 --.

Line 66, after "result" insert -- into one of the numbers 0 to 50 as shown in Table 1, and --.

Column 9,

Line 61, delete "them motor 108" and insert -- the motor 108 --.

Column 13

Line 35, delete "pushed do to" and insert -- pushed down to --.

Column 19,

Lines 9-10, delete "grove 110α (a telephoto end $110\alpha 1$)." and insert -- grove 101α (a telephoto end $101\alpha 1$). --.

Line 23, delete "groove 110α " and insert -- groove 101α --.

Line 25, delete "end 110 α 1" and insert -- end 101 α 1 --.

Signed and Sealed this

Sixth Day of June, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office